Error No. 5: EGAS 2

An error of the throttle reduction output 2 or its cabling.