

Error No. 7: Pressure Sensor / Pressure Switch 1

The minimum pressure in the hydraulic system has fallen short or a failure occurred in the electrical system of the pressure sensor or of the pressure switch of 3 bar or of its cabling. When using a two-cylinder hydraulic system the failure refers to the pressure sensor in cylinder 1.

With the articulation system HNG 16.5 the cylinder 1 is located in travel direction left and with the articulation system HG 15.3 .at the right hand side. A pressure switch is installed with the articulation system HNGK 9.2. From the serial number on the type label you can see what type of articulation system applies (e.g. 165).

