

Error No. 8: Bending Angle Potentiometer, mechanical

An error in the mechanical steering of the potentiometer.

