

Error No. 13: Pressure Range 1

The specified pressure in the hydraulic system has not been reached or an error occurred in the electrical system of the pressure sensor or of the pressure switch of 50 bar or of its cabling. When using a two-cylinder hydraulic system the failure refers to the pressure built-up in cylinder 1.

With the articulation system HNG 16.5 the cylinder 1 is located in travel direction left, while located right with the articulation system HNGK 9.2. A pressure switch is installed with the articulation system HNGK 9.2. From the serial number on the type label you can see what type of articulation system applies. (e.g. 165).

