

Error No. 6: Steering Angle Potentiometer, electric

An error in the electrical system of the potentiometer or its cabling.

