

Voith Turbo

VOITH

Service Accessories DIWA

150.00366911_EN

Diagnostic level

Edition: 2009-02-25

Table of Contents

Chapter 1	Description	1-1
1.1	Set level converter with RS232 interface with software ALADIN	1-1
1.2	Set level converter RS232 interface with software DIWAgnosis	1-1
1.3	Set level converter with USB interface with software ALADIN	1-2
1.4	Software ALADIN on CD-ROM	1-2
1.5	Voith Analyzer on CD-ROM	1-3
1.6	NEOMAN specific adapter cable	1-3
1.7	Diagnostic adapter OBD2	1-4

1 Description

1.1 Set level converter with RS232 interface with software ALADIN

The level converter with RS232 interface is the same as in DIWA.3 und DIWA.3E transmissions.

- Material number 151.00152920



Fig. 1-1 RS232 interface with software ALADIN

1.2 Set level converter RS232 interface with software DIWAgnosis

- Material number H59.250042



Fig. 1-2 RS232 interface with software DIWAgnosis

1.3 Set level converter with USB interface with software ALADIN

- Material number 151.00202120



Fig. 1-3 USB interface with Software ALADIN

1.4 Software ALADIN on CD-ROM

For customers already having a level converter.

- Material number 151.00097820




Fig. 1-4 Software ALADIN on CD-ROM

1.5 Voith Analyzer on CD-ROM

- Material number 151.00291820




Fig. 1-5 Voith Analyzer on CD-ROM

1.6 NEOMAN specific adapter cable

New cable for DIWA.5.

From TEPS

- Material number 150.00046710



Fig. 1-6 NEOMAN specific adapter cable

1.7 Diagnostic adapter OBD2

- Material number 150.00252710



Fig. 1-7 Diagnostic adapter OBD2

Voith Turbo GmbH & Co. KG

Alexanderstrasse 2

D-89522 Heidenheim

+49 7321 37 0

+49 7321 37 7618

service-diwa@voith.com

www.voithturbo.co

VOITH
Engineered reliability.